

Ready to share #1070	Jane Doe	2002 BMW 3 series
	jdoe123@gmail.com (336) 123-4567	WBAEV534X2KM21506 Odometer: 119202

EuroLube Service Inspection Sheet	
<b>Tire pressure, Wear &amp; Protection</b>	
	Adjusted pressure in rear to 32psi
<input checked="" type="checkbox"/>	Inspect Drive Belts
<input checked="" type="checkbox"/>	Brake Fluid/Condition
<input checked="" type="checkbox"/>	Power Steering Fluid
<input checked="" type="checkbox"/>	Coolant Level/Condition
<b>Washer Solvent Level</b>	
	added 1 quart
<input checked="" type="checkbox"/>	Transmission Fluid
<input checked="" type="checkbox"/>	Washer/Wiper Operation
<input checked="" type="checkbox"/>	Wiper Blade Condition
<b>Brake Pad Wear - Visual Inspection</b>	
	Front brake pads are below factory recommendations and should be replaced. See attached estimate.
<b>Check Exterior Lights</b>	
	Replaced left rear bulb.
<input checked="" type="checkbox"/>	Midtronics Battery Test
<input checked="" type="checkbox"/>	Reset Service Light
<input checked="" type="checkbox"/>	Pull Maintenance Book
<input checked="" type="checkbox"/>	Install oil sticker reminder/air pressure
<b>Any Body Damage, Missing Hub Caps, etc.</b>	
	Scratch on drivers side door

Notes: